


SITE ASSESSMENT - SPECIAL REPORT

PROPERTY INFORMATION	CLIENT INFORMATION
Project Name/Ref #: Not Provided BOUNSRCH STATE HWY 121 LEWISVILLE, TX 75067 Latitude/Longitude: (33.096146, 96.971451)	DORCAS BURNER CARTER AND BURGESS 3880 HULEN ST FORT WORTH, TX 76107

Site Distribution Summary	<i>within 1/8 mile</i>	<i>1/8 to 1/4 mile</i>	<i>1/4 to 1/2 mile</i>	<i>1/2 to 1 mile</i>
Agency / Database - Type of Records				
A) Databases searched to 1 mile:				
US EPA NPL National Priority List	0	0	0	0
US EPA CORRACTS RCRA Corrective Actions	0	0	0	0
STATE SPL State equivalent priority list	0	0	0	0
B) Databases searched to 1/2 mile:				
US EPA RCRA-TSD RCRA permitted treatment, storage, disposal facilities	1	0	0	-
STATE SCL State equivalent CERCLIS list	0	0	0	-
US EPA CERCLIS/ NFRAP Sites under review by US EPA	1	0	0	-
STATE/ REG/CO LUST Leaking Underground Storage Tanks	17	6	4	-
STATE/ REG/CO SWLF Solid waste landfills, incinerators, or transfer stations	2	0	0	-
C) Databases searched to 1/4 mile:				
STATE/ CO UST Registered underground storage tanks	44	8	-	-
STATE AST Registered aboveground storage tanks	4	0	-	-
D) Databases searched to 1/8 mile:				
US EPA GNRTR RCRA registered small or large generators of hazardous waste	9	-	-	-
US EPA/ STATE SPILLS ERNS and state spills lists	2	-	-	-



LIMITATION OF LIABILITY

Customer proceeds at its own risk in choosing to rely on VISTA services, in whole or in part, prior to proceeding with any transaction. VISTA cannot be an insurer of the accuracy of the information, errors occurring in conversion of data, or for customer's use of data. VISTA and its affiliated companies, officers, agents, employees and independent contractors cannot be held liable for accuracy, storage, delivery, loss or expense suffered by customer resulting directly or indirectly from any information provided by VISTA.

NOTES

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

SITE ASSESSMENT - SPECIAL REPORT

SITE INVENTORY

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B				C		D		
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR	SPILLS
1	TEXAS PARKS WILDLIFE DEPT. LEWISVILLE FISH HATCHE THE COLONY, TX 75056	1366995 0.00 MI NA									X			
2	EW JOHNSON CO INC 1495 N KEALY ST LEWISVILLE, TX 75057	5363911 0.00 MI NA											X	
2	METL-SPAN CORPORATION 1497 N KEALY LEWISVILLE, TX 75057	269663 0.00 MI NA											X	
3	DENTON COUNTY PRCNT 2 510 JONES ST LEWISVILLE, TX 75057	1386949 0.00 MI NA									X			
4	AVIS 1845 E IH--35 CARROLLTON, TX	3841956 0.00 MI NA							X					
4	BIG JACK'S GROCERY 1850 STEMMONS LEWISVILLE, TX 75067	11633595 0.00 MI NA							X					
5	NATL SWITCH GEAR SYSTEMS INC 649 FRANKLIN LEWISVILLE, TX 75057	5191433 0.00 MI NA										X		
6	DIAMOND SHAMROCK #785 4907 MAIN ST THE COLONY, TX 75056	1406082 0.00 MI NA									X			
6	THE COLONY TEXACO 4916 FM 423 THE COLONY, TX 75056	1797668 0.00 MI NA									X			
7	PIER 121 MARINA E HILL LAKE LEWISVILLE PARK THE COLONY, TX 75056	5198222 0.00 MI NA									X			
8	CALVERT'S BIG JACK 70337 LAKE PARK DR MILL ST THE COLONY, TX 75056	1369663 0.00 MI NA									X			
9	BIG JACKS I 35 @ FM 407 LEWISVILLE, TX 75067	11633286 0.00 MI NA									X			
10	LAKE PARK CONVENIENCE STORE 359 LAKE PLAZA RD LEWISVILLE, TX 75057	5737868 0.00 MI NA							X		X			



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #5

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B				C		D	
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
11	LEWISVILLE SERVICE OFFICE 2143 N STEMMONS LEWISVILLE, TX 75057	1405482 0.00 MI NA									X		
12	2097 N MCGEE LN LEWISVILLE, TX 75067	6640504 0.00 MI NA							X				
13	GENERAL TELEPHONE OF SOUTHWEST 1132 FM 407 N LEWISVILLE, TX 75067	169059 0.00 MI NA										X	
14	7-ELEVEN #26271 5010 MAIN ST THE COLONY, TX 75056	1804542 0.00 MI NA									X		
14	LAKESIDE CLNRS 5001 MAINE THE COLONY, TX 75056	1804541 0.00 MI NA										X	
15	SNAP-E-JACK #3 2997 STEMMONS LEWISVILLE, TX 75067	1364961 0.00 MI NA									X		
15	FORMER EZ SERVE #100100 2997 N STEMMONS LEWISVILLE, TX 75057	5110526 0.00 MI NA							X				
16	EAGLE POINT MARINA #1 EAGLE POINT DR LEWISVILLE, TX 75067	1392809 0.00 MI NA							X		X		
17	MURRAY CONSTRUCTION 249 SELMEYER LEWISVILLE, TX 75067	1377445 0.00 MI NA							X		X		
18	CITY SERVICE CENTER 948 HIGHLAND VILLAGE RD LEWISVILLE, TX 75067	5363769 0.00 MI NA									X		
18	HIGHLAND VILLAGE CITY OF 948 HIGHLAND VILLAGE RD LEWISVILLE, TX 75067	1099751 0.00 MI NA							X				
19	THE BAIT HOUSE/HAYS FINA HWY 423 STEWARTS CRE RD FRISCO, TX 75034	6641210 0.00 MI NA									X		
20	WESTLAKE PARK (LEWISVILLE LAKE) NO ADDRESS RECORDED IRVING, TX 75017	1782843 0.00 MI NA									X		
21	THOMPSON CO LAKE DALLAS SI 137 FOLLY BEACH RD LAKE DALLAS, TX 75065	423178 0.00 MI NA							X				
22	X-PRESSWAY FOOD STORE 203 MAIN ST LAKE DALLAS, TX 75065	6611581 0.00 MI NA									X		
22	CITY OF LAKE DALLAS 303 ALAMO LAKE DALLAS, TX 75065	1397951 0.00 MI NA									X		



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #6

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B				C		D	
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
23	G G AUTO SERVICE 312 MAIN ST LAKE DALLAS, TX 75065	1403425 0.00 MI NA									X		
23	CITY OF LAKE DALLAS FIRE DEPT 275 MAIN ST LAKE DALLAS, TX 75065	5547674 0.00 MI NA									X		
23	LAKE DALLAS CAFE TRU VALU HARDWARE 301 MAIN ST LAKE DALLAS, TX 75065	2578838 0.00 MI NA							X				
24	EXXON STORE #6-0381 8100 I-35 E DENTON, TX 76205	8533544 0.00 MI NA									X		
25	KELSOE TRACTOR CO (ALLSUPS) 102 MAIN ST LAKE DALLAS, TX 75065	4557428 0.00 MI NA							X				
26	LAKE DALLAS TELEPHONE COM 450 MAIN LAKE DALLAS, TX 75065	1406536 0.00 MI NA									X		
27	CITY LAKE DALLAS MAINTENANCE DEPT 351 BETCHAN DR LAKE DALLAS, TX 75065	5363385 0.00 MI NA							X				
28	LKDL RIN LW RPTR BLDG I 35 KELTON AVE LAKE DALLAS, TX 75065	6529798 0.00 MI NA									X		
29	LONE STAR PIPELINE 619 SHORE ST LAKE DALLAS, TX 75065	8534726 0.00 MI NA											X
30	LAKE DALLAS I.S.D. 425 E HUNDLEY DR LAKE DALLAS, TX 75065	6883422 0.00 MI NA									X		
31	RESIDENTIAL LOT 307 MARINA DR LAKE DALLAS, TX 75065	5738077 0.00 MI NA									X		
31	LAKE DALLAS BOAT CO, INC 708 E NICK ST LAKE DALLAS, TX 75065	1796216 0.00 MI NA									X		
32	D J GROCERY 631 S DENTON DR LAKE DALLAS, TX 75065	1399110 0.00 MI NA									X		
32	FAST BREAK #3(LAKE DALLAS SHAMROCK 401 S DENTON LAKE DALLAS, TX 75065	11631556 0.00 MI NA							X		X		
32	LAKELAND CITIES SHOPPING CTR/SPRITZ 603 S DENTON DR LAKE DALLAS, TX 75065	4091316 0.00 MI NA							X		X		
33	BEER BARN 307 W HUNDLEY DR LAKE DALLAS, TX 75065	5547520 0.00 MI NA									X		



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #7

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B				C		D	
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
33	SAMS GROCERY 307 W HUNDLEY DR LAKE DALLAS, TX 75065	1399105 0.00 MI NA						X					
34	PAYLESS CASHWAYS INC 500 N STEMMONS LAKE DALLAS, TX 75065	1391417 0.00 MI NA						X		X			
35	ROADIES 1002 S STEMMONS LAKE DALLAS, TX 75065	1813666 0.00 MI NA								X			
35	BOEING AEROSPACE ELECTR-CORINTH 7801 S STEMMONS LAKE DALLAS, TX 75065	52676 0.00 MI NA										X	
36	OSCAR RENDA 1500 TURBVILLE DENTON, TX 76205	8536207 0.00 MI NA									X		
37	SHAMROCK ENTERPRISES 423 BULADORA LN LITTLE ELM, TX 75068	4090941 0.00 MI NA				X						X	
38	HILLARD'S GROCERY 70334 507 SHADY SHORES RD LAKE DALLAS, TX 75065	6481432 0.00 MI NA								X			
39	VIDEO PLUS INC 200 SWISHER RD LAKE DALLAS, TX 75065	4899305 0.00 MI NA								X			
40	ROBINSON'S CONV STORE 201 KINGS RD FRISCO, TX 75034	7066281 0.00 MI NA								X			
41	LITTLE ELM ELEMENTARY MAIN STREET LAKESHORE LITTLE ELM, TX 75068	246415 0.00 MI NA								X			
42	LITTLE ELM ISD BUS FACILITY 411 LAKESHORE DR LITTLE ELM, TX 75068	6480941 0.00 MI NA									X		
43	MATLACK COMPANY *418 JONES AT UNITED RESI LONGVIEW, TX 75602	5795008 0.00 MI NA											X
44	CRAIG OLDEN INC 661 E SHAHAN'S PRAIRIE RD LITTLE ELM, TX 75068	1812473 0.00 MI NA								X			
45	STARLITE SIGN CO 7923 E MCKINNEY DENTON, TX 76208	3971154 0.00 MI NA									X	X	
46	CORPS OF ENGINEERS 1.0 MI S OF SH-380 W OF FM-424 MARSHALL, TX 75670	3050470 0.00 MI NA						X					
47	DENTON, CITY OF ADJACENT MOSELY RD, 1.2MI S OF US 38 MARSHALL, TX 75670	3048953 0.00 MI NA						X					



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #8

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B				C		D	
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
48	NAVO GENERAL STORE 4899 HWY 380 LITTLE ELM, TX 75068	6612126 0.00 MI NA									X		
49	ABLE FUEL INJECTION SVC 1419 CRESENT AVE LEWISVILLE, TX 75053	3017141 <0.01 MI S										X	
50	LEWISVILLE WATER PROD. FACILITY 1400 N COWAN LEWISVILLE, TX 75057	1389088 0.03 MI S									X		
51	MCGEE'S COUNTRY STORE 1298 FM RD 407 LEWISVILLE, TX 75067	1797534 0.04 MI S									X		
51	THE DEPOT 1175 JUSTIN RD FLOWER MOUND, TX 75028	3668592 0.08 MI S									X		
52	PHIL DILL BOATS INC 1520 N STEMMONS LEWISVILLE, TX 75057	328522 0.07 MI S							X		X		
53	LAKE DALLAS SERVICE CENTER 3100 S GARRISON LAKE DALLAS, TX 75065	1399601 0.08 MI SW									X		
54	GTSW - LEWISVILLE PLANT FACILITY 1132 FM 407 LEWISVILLE, TX 75067	5172878 0.10 MI S									X		
54	GTE LEWISVILLE FACILITY 1132 FM 407 LEWISVILLE, TX 75067	1798130 0.10 MI S							X		X		

MAP ID	SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)	VISTA ID DISTANCE DIRECTION	A			B			C		D		
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
55	JOE'S COUNTRY STORE 7616 N MAIN THE COLONY, TX 75056	6475880 0.13 MI SE							X		X		
56	TRINTY CAR WASH 1450 W JUSTIN RD LEWISVILLE, TX 75067	6883566 0.14 MI S									X		
56	WEST TEX AUTO TIRE 1425 JUSTIN RD #350 LEWISVILLE, TX 75067	1408958 0.15 MI S							X		X		
56	EXXON STORE 6-0357 1501 W FM 407 LEWISVILLE, TX 75067	7066672 0.17 MI S									X		



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #9

MAP ID	SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)	VISTA ID DISTANCE DIRECTION	A			B			C		D		
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
57	KEN'S QUIK MART FOODS 7420 MAIN ST THE COLONY, TX 75056	6883806 0.16 MI SE								X			
58	MOBIL #12-147 6262 W MAIN ST THE COLONY, TX 75056	6475878 0.17 MI SE						X					
59	LEWISVILLE CITY OF 1100 N KEALY LEWISVILLE, TX 75057	2574045 0.19 MI S						X		X			
60	UAC OF GARLAND, INC. 7228 MAIN ST THE COLONY, TX 75056	2579974 0.20 MI SE								X			
60	CLOSED FACILITY 7228 N MAIN ST THE COLONY, TX 75056	2579973 0.20 MI SE						X					
61	C B EXPRESS 4250 E UNIVERSITY DENTON, TX 76208	4555510 0.24 MI NW								X			
62	STOP N GO #1127 4610 FM 423 THE COLONY, TX 75056	5109461 0.24 MI SE						X					

MAP ID	SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)	VISTA ID DISTANCE DIRECTION	A			B			C		D		
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR
63	HOWDY DOODY GRO 1026 N MILL LEWISVILLE, TX 75057	6982928 0.28 MI S							X				
63	CLOSED HOWDY-DOODY STORE 1026 N MILL ST LEWISVILLE, TX 75057	2577973 0.28 MI S							X				
64	VILLAGE FORD 1144 N STEMMONS FRWY LEWISVILLE, TX 75057	162121 0.35 MI S							X			•	
65	NORTHWEST BUTANE 9001 FM 423 FRISCO, TX 75034	1798136 0.41 MI E							X		•		



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #10

MAP ID	SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)	VISTA ID DISTANCE DIRECTION	A			B			C		D			
			NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR	SPILLS
No Records Found														



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #11

UNMAPPED SITES	VISTA ID	A			B				C		D		
		NPL	CORRACTS	SPL	TSD	SCL	CERCLIS/NFRAP	LUST	SWLF	UST	AST	GNRTR	SPILLS
TRU-VALU HARDWARE MAIN ST LAKE DALLAS, TX 75065	1371207									X			
LAKE CITIES MUA N END LAKEVIEW DR LAKE DALLAS, TX 75065	1796228									X			
ARGYLE ISD PO BOX 989 ARGYLE, TX 76226	1376368									X			
TECHNICIANS ON WHEELS LAKE DALLAS, TX 75065	8509811												X
H L MIZE BOX 846 LAKE DALLAS, TX 75065	196648						X						
HomeBuilders Ready Mix Inc HWY 121 CAMEY COMMUNIT LEWISVILLE, TX 75067	1794004									X			



An 'X' meets search criteria; a dot exceeds search criteria.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #12

SITE ASSESSMENT - SPECIAL REPORT

DETAILS

PROPERTY AND THE ADJACENT AREA (within 1/8 mile)

VISTA Address*:	TEXAS PARKS WILDLIFE DEPT. LEWISVILLE FISH HATCHE THE COLONY, TX 75056	VISTA ID#:	1366995
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0003293
Agency Address:	TEXAS PARKS WILDLIFE DEPT. LEWISVILLE FISH HATCHE LEWISVILLE, TX 75067		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	22	Tank Piping:	SINGLE WALL
Tank Size (Units):	550 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1971		
Tank Removal Date:	08/01/1993		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: US ARMY CORP OF ENGINEERS LAERFRR 3LEWISVILLE, TX 75056		

Map ID

1

VISTA Address*:	EW JOHNSON CO INC 1495 N KEALY ST LEWISVILLE, TX 75057	VISTA ID#:	5363911
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TX0000930909
Agency Address:	SAME AS ABOVE		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

Map ID

2

VISTA Address*:	METL-SPAN CORPORATION 1497 N KEALY LEWISVILLE, TX 75057	VISTA ID#:	269663
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TXD102592383
Agency Address:	METL-SPAN CORPORATION 1497 N KEALY LEWISVILLE, TX 75067		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

Map ID

2



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #13

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Map ID

3

VISTA Address*:	DENTON COUNTY PRCNT 2 510 JONES ST LEWISVILLE, TX 75057	VISTA ID#:	1386949
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

AST - Above Ground Storage Tank / SRC# 5627	Agency ID:	0025456
--	------------	---------

Agency Address:	DENTON COUNTY PRCNT 2 510 JONES ST LEWISVILLE, TX 75067
Underground Tanks:	2
Aboveground Tanks:	1
Tanks Removed:	NOT REPORTED

Tank ID:	AA	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NOT AVAILABLE
Tank Age:	13	Tank Piping:	UNKNOWN
Tank Size (Units):	2500 (GALLONS)	Tank Material:	UNKNOWN

Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL

Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL

Tank ID#:	AA
-----------	----

Tank Installed Date / Age:	01/01/1986
----------------------------	------------

Description / Comment:	MONITOR TYPE: NOT APPLICABLE
------------------------	------------------------------

Description / Comment:	OWNER: DENTON COUNTY401 W HICKORYDENTON, TX 76201
------------------------	---

Tank ID#:	U1
-----------	----

Tank Installed Date / Age:	01/01/1981
----------------------------	------------

Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE
------------------------	---------------------------------------

Description / Comment:	OWNER: DENTON COUNTY401 W HICKORYDENTON, TX 76201
------------------------	---

Tank ID#:	U2
-----------	----

Tank Installed Date / Age:	01/01/1981
----------------------------	------------

Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE
------------------------	---------------------------------------

Description / Comment:	OWNER: DENTON COUNTY401 W HICKORYDENTON, TX 76201
------------------------	---

VISTA Address*:	AVIS 1845 E IH--35 CARROLLTON, TX	VISTA ID#:	3841956
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

4

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
--	----------------	-----

Agency Address:	SAME AS ABOVE
-----------------	---------------

Facility ID:	0023809
--------------	---------

Leak ID#:	105220
-----------	--------

Leak Report Date:	11/21/92
-------------------	----------

Region / District:	ARLINGTON
--------------------	-----------

Responsible Party:	HAYES LEASING CO INC
--------------------	----------------------

Description / Comment:	MEDIA AFFECTED: GW IMPACT, PUB/DOM WATER SUPPLY WELL W/IN .25 -.5 MIREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: PO BOX 569650,DALLAS,TX,753569650,214/574-4110
------------------------	---



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #14

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	BIG JACK'S GROCERY 1850 STEMMONS LEWISVILLE, TX 75067	VISTA ID#:	11633595
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0008171		
Leak ID#:	113796		
Leak Report Date:	12/4/98		
Region / District:	ARLINGTON		
Responsible Party:	METRO PETRO RENTALS INC		
Description / Comment:	MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDICATION STATUS: INCIDENT REPORTED, INITIAL DIRECTIVES NOT YET ISSUED RESPONSIBLE PARTY INFO: 728 FORT WORTH DR, DENTON, TX, 76201, 940/382-5644		

Map ID

4

VISTA Address*:	NATL SWITCH GEAR SYSTEMS INC 649 FRANKLIN LEWISVILLE, TX 75057	VISTA ID#:	5191433
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TX0000237644
Agency Address:	NATIONAL SWITCH GEAR SYS INC 649 FRANKLIN LEWISVILLE, TX 75057		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

Map ID

5

VISTA Address*:	DIAMOND SHAMROCK #785 4907 MAIN ST THE COLONY, TX 75056	VISTA ID#:	1406082
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0046437
Agency Address:	DIAMOND SHAMROCK #785 4907 MAIN ST THE COLONY, TX 75086		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	13	Tank Piping:	DOUBLE WALL, SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	13	Tank Piping:	DOUBLE WALL, SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	13	Tank Piping:	DOUBLE WALL, SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	09/01/1986		
Description / Comment:	TANK MONITOR: STAT. INVENTORY RECONCILIATION (SIR) PIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: DIAMOND SHAMROCK REFINING MKTPO BOX 696000 SAN ANTONIO, TX 782696000		
Tank ID#:	U2		
Tank Installed Date / Age:	09/01/1986		
Description / Comment:	TANK MONITOR: STAT. INVENTORY RECONCILIATION (SIR) PIPE MONITOR: LINE LEAK DETECTORS		

Map ID

6



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #15

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Description / Comment:	OWNER: DIAMOND SHAMROCK REFINING MKTPO BOX 696000SAN ANTONIO, TX 782696000
Tank ID#:	U3
Tank Installed Date / Age:	09/01/1986
Description / Comment:	TANK MONITOR: STAT. INVENTORY RECONCILIATION (SIR)PIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: DIAMOND SHAMROCK REFINING MKTPO BOX 696000SAN ANTONIO, TX 782696000

VISTA Address*:	THE COLONY TEXACO 4916 FM 423 THE COLONY, TX 75056	VISTA ID#:	1797668
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0039401

Map ID

6

Agency Address:	SAME AS ABOVE		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	09/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U2		
Tank Installed Date / Age:	09/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U3		
Tank Installed Date / Age:	09/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U4		
Tank Installed Date / Age:	09/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #16

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	PIER 121 MARINA E HILL LAKE LEWISVILLE PARK THE COLONY, TX 75056	VISTA ID#:	5198222
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

7

STATE UST - State Underground Storage Tank / SRC# 5627	Agency ID:	0024943
---	------------	---------

Agency Address:		PIER 121 MARINA E HILL LAKE LEWISVILLE PARK LEWISVILLE, TX 75067	
Underground Tanks:		3	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	33	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	33	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	33	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1966		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: GARRETT PLACE, INC. 11226 INDIAN TRAIL DALLAS, TX 752293518		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1966		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: GARRETT PLACE, INC. 11226 INDIAN TRAIL DALLAS, TX 752293518		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1966		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: GARRETT PLACE, INC. 11226 INDIAN TRAIL DALLAS, TX 752293518		

VISTA Address*:	CALVERT'S BIG JACK 70337 LAKE PARK DR MILL ST THE COLONY, TX 75056	VISTA ID#:	1369663
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

8

STATE UST - State Underground Storage Tank / SRC# 5627	Agency ID:	0006258
---	------------	---------

Agency Address:		CALVERT'S BIG JACK 70337 LAKE PARK DR MILL ST LEWISVILLE, TX 75056	
Underground Tanks:		3	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	17	Tank Piping:	STEEL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #17

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	17	Tank Piping:	STEEL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	17	Tank Piping:	STEEL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1982		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: AMBREEN AFSHEEN ENT101 LAKE PARKLEWISVILLE, TX 75057		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1982		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: AMBREEN AFSHEEN ENT101 LAKE PARKLEWISVILLE, TX 75057		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1982		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: AMBREEN AFSHEEN ENT101 LAKE PARKLEWISVILLE, TX 75057		

VISTA Address*:	BIG JACKS I 35 @ FM 407 LEWISVILLE, TX 75067	VISTA ID#:	11633286
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0008171

Map ID

9

Agency Address:		SAME AS ABOVE	
Underground Tanks:		4	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1985		
Description / Comment:	TANK MONITOR: VAPOR MONITORINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: METRO PETRO RENTALS INC728 F. W. DRDENTON, TX 76201		
Tank ID#:	U2		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #18

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank Installed Date / Age:	01/01/1985
Description / Comment:	TANK MONITOR: VAPOR MONITORING PIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: METRO PETRO RENTALS INC 728 F. W. DR DENTON, TX 76201
Tank ID#:	U3
Tank Installed Date / Age:	01/01/1985
Description / Comment:	TANK MONITOR: VAPOR MONITORING PIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: METRO PETRO RENTALS INC 728 F. W. DR DENTON, TX 76201
Tank ID#:	U4
Tank Installed Date / Age:	01/01/1985
Description / Comment:	TANK MONITOR: VAPOR MONITORING PIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: METRO PETRO RENTALS INC 728 F. W. DR DENTON, TX 76201

VISTA Address*:	LAKE PARK CONVENIENCE STORE 359 LAKE PLAZA RD LEWISVILLE, TX 75057	VISTA ID#:	5737868
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A

Map ID

10

Agency Address:	SAME AS ABOVE		
Facility ID:	0020638		
Leak ID#:	113629		
Leak Report Date:	7/11/97		
Region / District:	ARLINGTON		
Responsible Party:	LAKE PARK PLAZA JOINT VENTURE		
Description / Comment:	MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDIATION STATUS: PHASE 2 IN PROGRESS RESPONSIBLE PARTY INFO: 2061 JUSTIN RD SUITE 300, LEWISVILLE, TX, 75077, 972/966-1111		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0020638
Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1983		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: ALI, MOHAMMED 359 LAKE PARK RD LEWISVILLE, TX 75057 2307		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1983		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: ALI, MOHAMMED 359 LAKE PARK RD LEWISVILLE, TX 75057 2307		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #19

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID#:	U3
Tank Installed Date / Age:	01/01/1983
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: TIGHTNESS TESTING
Description / Comment:	OWNER: ALI, MOHAMMED359 LAKE PARK RDLewisville, TX 750572307

VISTA Address*:	LEWISVILLE SERVICE OFFICE 2143 N STEMMONS LEWISVILLE, TX 75057	VISTA ID#:	1405482
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

11

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0045796
Agency Address:	LEWISVILLE SERVICE OFFICE 2143 N STEMMONS LEWISVILLE, TX 75067		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	10	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	4000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1988		
Tank Removal Date:	08/01/1998		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING, TX 75062		

VISTA Address*:	2097 N MCGEE LN LEWISVILLE, TX 75067	VISTA ID#:	6640504
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

12

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Leak ID#:	091756		
Leak Report Date:	2/18/88		
Region / District:	ARLINGTON		
Responsible Party:	SAN JUAN POOLS OF TEXAS		
Description / Comment:	MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORSREMEDATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: PO BOX 703301,DALLAS, TX,75370,214/242-9595		

VISTA Address*:	GENERAL TELEPHONE OF SOUTHWEST 1132 FM 407 N LEWISVILLE, TX 75067	VISTA ID#:	169059
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

13

RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TXD981154644
Agency Address:	SAME AS ABOVE		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #20

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	7-ELEVEN #26271 5010 MAIN ST THE COLONY, TX 75056	VISTA ID#:	1804542
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

14

STATE UST - State Underground Storage Tank / SRC# 5627

Agency ID: 0009225

Agency Address:	7-ELEVEN #26271 5010 MAIN ST THE COLONY, TX 76056		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	05/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SOUTHLAND CORPORATIONPO BOX 711DALLAS, TX 75221		
Tank ID#:	U2		
Tank Installed Date / Age:	05/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SOUTHLAND CORPORATIONPO BOX 711DALLAS, TX 75221		
Tank ID#:	U3		
Tank Installed Date / Age:	05/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SOUTHLAND CORPORATIONPO BOX 711DALLAS, TX 75221		

VISTA Address*:	LAKESIDE CLNRS 5001 MAINE THE COLONY, TX 75056	VISTA ID#:	1804541
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

14

RCRA-SmGen - RCRA-Small Generator / SRC# 5596

EPA ID: TXD988022265

Agency Address:	SAME AS ABOVE		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

VISTA Address*:	SNAP-E-JACK #3 2997 STEMMONS LEWISVILLE, TX 75067	VISTA ID#:	1364961
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

15

STATE UST - State Underground Storage Tank / SRC# 5627

Agency ID: 0000960

Agency Address:	SAME AS ABOVE		
Underground Tanks:	5		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	3		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #21

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	18	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	4	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	18	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	4	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	18	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	01/01/1994		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SNAP-E-SACK, INC2997 N STEMMONSLEWISVILLE, TX 75067		
Tank ID#:	U1A		
Tank Installed Date / Age:	05/01/1995		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SNAP-E-SACK, INC2997 N STEMMONSLEWISVILLE, TX 75067		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	01/01/1994		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SNAP-E-SACK, INC2997 N STEMMONSLEWISVILLE, TX 75067		
Tank ID#:	U2A		
Tank Installed Date / Age:	05/01/1995		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SNAP-E-SACK, INC2997 N STEMMONSLEWISVILLE, TX 75067		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	01/01/1994		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: SNAP-E-SACK, INC2997 N STEMMONSLEWISVILLE, TX 75067		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #22

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	FORMER EZ SERVE #100100 2997 N STEMMONS LEWISVILLE, TX 75057	VISTA ID#:	5110526
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:		FORMER EZ SERVE #100100 2997 N STEMMONS LEWISVILLE, TX	
Facility ID:		0000960	
Leak ID#:		108311	
Leak Report Date:		1/12/94	
Region / District:		ARLINGTON	
Responsible Party:		E Z SERVE MANAGEMENT CO	
Description / Comment:		MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSED RESPONSIBLE PARTY INFO: 2500 N LOOP W #600, HOUSTON, TX, 77092, 713/684-4300	

Map ID

15

VISTA Address*:	EAGLE POINT MARINA #1 EAGLE POINT DR LEWISVILLE, TX 75067	VISTA ID#:	1392809
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:		EAGLE POINT MARINA #1 EAGLE POINT DR LEWISVILLE, TX 75057	
Facility ID:		0031855	
Leak ID#:		113640	
Region / District:		ARLINGTON	
Responsible Party:		TRETT-ENTERPRISES INC	
Description / Comment:		REMEDATION STATUS: INCIDENT REPORTED, INITIAL DIRECTIVES NOT YET ISSUED RESPONSIBLE PARTY INFO: #1 EAGLE POINT DR, LEWISVILLE, TX, 75057, 972/436-6561	

Map ID

16

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0031855
Agency Address:		EAGLE POINT MARINA #1 EAGLE POINT DR LEWISVILLE, TX 75057	
Underground Tanks:		3	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	UNKNOWN	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: TRETT-ENTERPRISES, INC. #1 EAGLE POINT DR LEWISVILLE, TX 75057		
Tank ID#:	U2		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #23

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank Installed Date / Age:	UNRECORDED
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: TRETT-ENTERPRISES, INC.#1 EAGLE POINT DRLEWISVILLE, TX 75057
Tank ID#:	U3
Tank Installed Date / Age:	UNRECORDED
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: TRETT-ENTERPRISES, INC.#1 EAGLE POINT DRLEWISVILLE, TX 75057

VISTA Address*:	MURRAY CONSTRUCTION 249 SELLMEYER LEWISVILLE, TX 75067	VISTA ID#:	1377445
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

17

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	MURRAY CONSTRUCTION 249 SELLMEYER HIGHLAND VILLAGE, TX		
Facility ID:	0014795		
Leak ID#:	108716		
Leak Report Date:	9/22/94		
Region / District:	ARLINGTON		
Responsible Party:	MURRAY CONSTRUCTION CO INC		
Description / Comment:	MEDIA AFFECTED: GW IMPACT, PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25MIREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: 515 N KEALY AVE,LEWISVILLE, TX,75067,214/436-4566		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0014795
Agency Address:	MURRAY CONSTRUCTION CO. INC. 249 SELLMEYER HIGHLAND VILLAGE, TX 75067		
Underground Tanks:	2		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	2		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	SINGLE WALL
Tank Size (Units):	5000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	SINGLE WALL
Tank Size (Units):	500 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	09/01/1994		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: MURRAY CONSTRUCTION CO, INC515 N KEALY AVELEWISVILLE, TX 75067		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	09/01/1994		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: MURRAY CONSTRUCTION CO, INC515 N KEALY AVELEWISVILLE, TX 75067		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #24

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	CITY SERVICE CENTER 948 HIGHLAND VILLAGE RD LEWISVILLE, TX 75067	VISTA ID#:	5363769
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

18

STATE UST - State Underground Storage Tank / SRC# 5627

Agency ID: 0012894

Agency Address:	CITY SERVICE CENTER 948 HIGHLAND VILLAGE RD HIGHLAND VILLAGE, TX 75067		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	15	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	8	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	8	Tank Piping:	SINGLE WALL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	05/01/1991		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF HIGHLAND VILLAGE948 HIGHLAND VILLAGE RDHIGHLAND VILLAGE, TX 750676799		
Tank ID#:	U1A		
Tank Installed Date / Age:	05/01/1991		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: CITY OF HIGHLAND VILLAGE948 HIGHLAND VILLAGE RDHIGHLAND VILLAGE, TX 750676799		
Tank ID#:	U2A		
Tank Installed Date / Age:	05/01/1991		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: CITY OF HIGHLAND VILLAGE948 HIGHLAND VILLAGE RDHIGHLAND VILLAGE, TX 750676799		

VISTA Address*:	HIGHLAND VILLAGE CITY OF 948 HIGHLAND VILLAGE RD LEWISVILLE, TX 75067	VISTA ID#:	1099751
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

18

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626

EPA/Agency ID: N/A

Agency Address:	CITY OF HIGHLAND VILLAGE 948 HIGHLAND VILLAGE RD HIGHLAND VILLAGE, TX 75067		
Facility ID:	0012894		
Leak ID#:	099166		
Leak Report Date:	6/4/91		
Region / District:	ARLINGTON		
Responsible Party:	CITY OF HIGHLAND VILLAGE		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #25

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Description / Comment:

*MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS
REMEDICATION STATUS: PHASE 2 IN PROGRESS
RESPONSIBLE PARTY INFO: 948 HIGHLAND VILLAGE RD, HIGHLAND VILLAGE, TX, 750670000, 972/317-2558*

VISTA Address*:	THE BAIT HOUSE/HAYS FINA HWY 423 STEWARTS CRE RD FRISCO, TX 75034	VISTA ID#:	6641210
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0049819

Map ID

19

Agency Address:		SAME AS ABOVE	
Underground Tanks:		4	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1975		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LEVSEY, GLENDART 2, BOX 375-CFRISCO, TX 75034		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1975		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LEVSEY, GLENDART 2, BOX 375-CFRISCO, TX 75034		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1975		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LEVSEY, GLENDART 2, BOX 375-CFRISCO, TX 75034		
Tank ID#:	U4		
Tank Installed Date / Age:	01/01/1975		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LEVSEY, GLENDART 2, BOX 375-CFRISCO, TX 75034		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #26

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	WESTLAKE PARK (LEWISVILLE LAKE) NO ADDRESS RECORDED IRVING, TX 75017	VISTA ID#:	1782843
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0006768
Agency Address:	WESTLAKE PARK (LEWISVILLE LAKE) NO ADDRESS RECORDED LEWISVILLE, TX 75017		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	ABANDONED
Tank Contents:	EMPTY	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	NOT REPORTED (GALLONS)	Tank Material:	UNKNOWN
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	04/01/1984		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CORPS OF ENGINEERS 1801 N MILLEWISVILLE, TX 75017		

Map ID

20

VISTA Address*:	THOMPSON CO LAKE DALLAS SI 137 FOLLY BEACH RD LAKE DALLAS, TX 75065	VISTA ID#:	423178
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
NFRAP / SRC# 5595		EPA ID:	TXD980697023
Agency Address:	THOMPSON CO LAKE DALLAS SITE 137 FOLLY BEACH RD LAKE DALLAS, TX 75065		
EPA Region:	6		
Congressional District:	0		
Federal Facility:	Agency Code ()		
Facility Ownership:	OTHER		
Site Incident Category:	unknown		
Federal Facility Docket:	SITE IS NOT INCLUDED ON THE DOCKET		
NPL Status:	NOT ON NPL		
Incident Type:	Unknown		
Proposed NPL Update #:	0		
Final NPL Update #:	0		
Financial Management System ID:	NOT REPORTED		
Latitude:	0		
Longitude:	0		
Lat/Long Source:	Agency Code ()		
Lat/Long Accuracy:	Unknown		
Dioxin Tier:	Unknown		
USGS Hydro Unit:	12030103		
RCRA Indicator:	Unknown		
Unit Id:	0		
Unit Name:	ENTIRE SITE		
Type:	DISCOVERY	Lead Agency:	EPA FUND-FINANCED
Qualifier:	UNKNOWN	Category:	Unknown
Name:	NOT REPORTED	Actual Start Date:	NOT REPORTED
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN

Map ID

21



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #27

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Type:	PRELIMINARY ASSESSMENT	Lead Agency:	EPA FUND-FINANCED
Qualifier:	NO FURTHER REMEDIAL ACTION PLANNED	Category:	Unknown
Name:	NOT REPORTED	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN

VISTA Address*:	X-PRESSWAY FOOD STORE 203 MAIN ST LAKE DALLAS, TX 75065	VISTA ID#:	6611581
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0038669

Map ID

22

Agency Address:	SAME AS ABOVE		
Underground Tanks:	2		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	25	Tank Piping:	STEEL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	25	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1974		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: SHUJA, KAMAL 203 MAIN ST LAKE DALLAS, TX 75065		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1974		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: SHUJA, KAMAL 203 MAIN ST LAKE DALLAS, TX 75065		

VISTA Address*:	CITY OF LAKE DALLAS 303 ALAMO LAKE DALLAS, TX 75065	VISTA ID#:	1397951
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0037390

Map ID

22

Agency Address:	SAME AS ABOVE		
Underground Tanks:	2		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	2		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	20	Tank Piping:	STEEL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	23	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1975		
Tank Removal Date:	01/01/1995		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #28

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Description / Comment:	OWNER: CITY OF LAKE DALLASPO BOX 368LAKE DALLAS, TX 75065
Tank ID#:	U2
Tank Installed Date / Age:	01/01/1972
Tank Removal Date:	01/01/1995
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: CITY OF LAKE DALLASPO BOX 368LAKE DALLAS, TX 75065

VISTA Address*:	G G AUTO SERVICE 312 MAIN ST LAKE DALLAS, TX 75065	VISTA ID#:	1403425
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

23

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0043391
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	USED OIL	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	700 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: G G AUTO SERVICEPO BOX 1316LAKE DALLAS, TX 750651316		

VISTA Address*:	CITY OF LAKE DALLAS FIRE DEPT 275 MAIN ST LAKE DALLAS, TX 75065	VISTA ID#:	5547674
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

23

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0066842
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	EMPTY	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	SINGLE WALL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	01/01/1995		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LAKE DALLASPO BOX 368LAKE DALLAS, TX 75065		

VISTA Address*:	LAKE DALLAS CAFE TRU VALU HARDWARE 301 MAIN ST LAKE DALLAS, TX 75065	VISTA ID#:	2578838
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

23

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0007909		
Leak ID#:	101074		
Leak Report Date:	12/2/91		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #29

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Region / District:	ARLINGTON
Responsible Party:	AMERICAN FEDERAL BANK
Description / Comment:	MEDIA AFFECTED: MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAPREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: PO BOX 809094,DALLAS,TX,75380,214/450-1800

VISTA Address*:	EXXON STORE #6-0381 8100 I-35 E DENTON, TX 76205	VISTA ID#:	8533544
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0070789

Map ID

24

Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	1	Tank Piping:	DOUBLE WALL,DOUBLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	1	Tank Piping:	DOUBLE WALL,DOUBLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	1	Tank Piping:	DOUBLE WALL,DOUBLE WALL
Tank Size (Units):	12000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1998		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON,TX 772104386		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1998		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON,TX 772104386		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1998		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON,TX 772104386		

VISTA Address*:	KELSOE TRACTOR CO (ALLSUPS) 102 MAIN ST LAKE DALLAS, TX 75065	VISTA ID#:	4557428
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A

Map ID

25

Agency Address:	KELSOE TRACTOR CO (ALLSUPS) 102 MAIN ST LAKE DALLAS, TX 75065
Facility ID:	0045870
Leak ID#:	107630
Leak Report Date:	8/17/93
Region / District:	ARLINGTON
Responsible Party:	KELSOE TRACTOR CO INC



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #30

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Description / Comment:

MEDIA AFFECTED: GW IMPACT, PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN
0.25MIREMEDIATION STATUS: PHASE 3 IN PROGRESS AND QUARTERLY MONITORING IN
PROGRESS RESPONSIBLE PARTY INFO: P.O. DRAWER R, DENTON, TX, 76202, 817/387-3804

VISTA Address*:	LAKE DALLAS TELEPHONE COM		VISTA ID#:	1406536
	450 MAIN		Distance/Direction:	0.00 MI / NA
	LAKE DALLAS, TX 75065		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627			Agency ID:	0046936
Agency Address:		SAME AS ABOVE		
Underground Tanks:		1		
Aboveground Tanks:		NOT REPORTED		
Tanks Removed:		1		
Tank ID:	UCO-1	Tank Status:	REMOVED	
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR	
Tank Age:	11	Tank Piping:	ANTI-CORROSIVE	
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL	
Tank ID#:	UCO-1			
Tank Installed Date / Age:	01/01/1980			
Tank Removal Date:	07/01/1991			
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE			
Description / Comment:	OWNER: LAKE DALLAS TELEPHONE 450 MAIN ST LAKE DENTON, TX 75065			

Map ID

26

VISTA Address*:	CITY LAKE DALLAS MAINTENANCE DEPT		VISTA ID#:	5363385
	351 BETCHAN DR		Distance/Direction:	0.00 MI / NA
	LAKE DALLAS, TX 75065		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626			EPA/Agency ID:	N/A
Agency Address:		CITY LAKE DALLAS MAINTENANCE DEPT 351 BETCHAN DR LAKE DALLAS, TX		
Facility ID:		0037390		
Leak ID#:		109035		
Leak Report Date:		1/13/95		
Region / District:		ARLINGTON		
Responsible Party:		CITY OF LAKE DALLAS		
Description / Comment:		MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDIATION STATUS: PHASE 3 IN PROGRESS RESPONSIBLE PARTY INFO: PO BOX 368, LAKE DALLAS, TX, 75065, 817/497-2226		

Map ID

27

VISTA Address*:	LKDL RIN LW RPTR BLDG		VISTA ID#:	6529798
	I 35 KELTON AVE		Distance/Direction:	0.00 MI / NA
	LAKE DALLAS, TX 75065		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627			Agency ID:	0019433
Agency Address:		SAME AS ABOVE		
Underground Tanks:		1		
Aboveground Tanks:		NOT REPORTED		
Tanks Removed:		1		
Tank ID:	U1	Tank Status:	REMOVED	
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR	
Tank Age:	11	Tank Piping:	STEEL	
Tank Size (Units):	550 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC	
Tank ID#:	U1			
Tank Installed Date / Age:	01/01/1982			

Map ID

28



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #31

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank Removal Date:	11/01/1993
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE
Description / Comment:	OWNER: SOUTHWESTERN BELL TELEPHONE COTHRREE BELL PLAZADALLAS, TX 752655521

VISTA Address*:	LONE STAR PIPELINE 619 SHORE ST LAKE DALLAS, TX 75065	VISTA ID#:	8534726
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

29

ERNS - Emergency Response Notification System / SRC# 5598		Agency ID:	398866
Agency Address:	LONE STAR PIPELINE 619 SHORE ST LAKE DALLAS, TX		
Spill Date Time:	AUGUST 11, 2000 09:00:00 AM		
Case Number:	398866		
Spill Location:	619 SHORE ST		
Discharger Name:	LONE STAR PIPELINE		
Discharger Org:	LONE STAR PIPELINE		
Material Spilled:	NATURAL GAS, 0.00 (UNK)		
Fields Not Reported:	Source Agency, Discharger Phone, Waterway Affected		
Air Release:	Land Release:	Water Release:	Ground Release:
YES	NO	NO	NO
		Facility Release:	Other Release:
		NO	NO

VISTA Address*:	LAKE DALLAS I.S.D. 425 E HUNDLEY DR LAKE DALLAS, TX 75065	VISTA ID#:	6883422
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

30

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0037417
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	27	Tank Piping:	SINGLE WALL
Tank Size (Units):	2005 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1972		
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROL PIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: LAKE DALLAS I.S.D. PO BOX 548 LAKE DALLAS, TX 75065		

VISTA Address*:	RESIDENTIAL LOT 307 MARINA DR LAKE DALLAS, TX 75065	VISTA ID#:	5738077
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

31

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0067459
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	UNKNOWN	Leak Monitoring:	NO MONITOR
Tank Age:	8	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	550 (GALLONS)	Tank Material:	UNKNOWN



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #32

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID#:	U1
Tank Installed Date / Age:	08/01/1987
Tank Removal Date:	12/01/1995
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: ESTATE OF J FAYE SMITH12222 MERIT DRDALLAS, TX 75251

VISTA Address*:	LAKE DALLAS BOAT CO, INC 708 E NICK ST LAKE DALLAS, TX 75065	VISTA ID#:	1796216
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0050431

Map ID

31

Agency Address:	SAME AS ABOVE		
Underground Tanks:	2		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	10	Tank Piping:	STEEL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	10	Tank Piping:	STEEL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1989		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: LAKEVIEW MARINA/LAKE DALLAS BOATPO BOX 397LAKE DALLAS, TX 75065		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1989		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: LAKEVIEW MARINA/LAKE DALLAS BOATPO BOX 397LAKE DALLAS, TX 75065		

VISTA Address*:	D J GROCERY 631 S DENTON DR LAKE DALLAS, TX 75065	VISTA ID#:	1399110
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0038658

Map ID

32

Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #33

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	24	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	09/01/1975		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: KIM, EDWARD JONGP.O. BOX 1318LAKE DALLAS, TX 75065		
Tank ID#:	U2		
Tank Installed Date / Age:	09/01/1975		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: KIM, EDWARD JONGP.O. BOX 1318LAKE DALLAS, TX 75065		
Tank ID#:	U3		
Tank Installed Date / Age:	09/01/1975		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: KIM, EDWARD JONGP.O. BOX 1318LAKE DALLAS, TX 75065		

VISTA Address*:	FAST BREAK #3(LAKE DALLAS SHAMROCK 401 S DENTON LAKE DALLAS, TX 75065	VISTA ID#:	11631556
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

32

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0008180		
Leak ID#:	113793		
Leak Report Date:	12/4/98		
Region / District:	ARLINGTON		
Responsible Party:	U S R COMPANY		
Description / Comment:	REMEDATION STATUS: INCIDENT REPORTED, INITIAL DIRECTIVES NOT YET ISSUEDRESPONSIBLE PARTY INFO: 728 FORT WORTH DR,DENTON,TX,76201,940/382-5644		
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0008180
Agency Address:	FAST BREAK #3 401 S DENTON LAKE DALLAS, TX 75065		
Underground Tanks:	5		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	4		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	26	Tank Piping:	STEEL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	2	Tank Piping:	SINGLE WALL
Tank Size (Units):	20000 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	26	Tank Piping:	STEEL
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: **May 6, 1999**

Page #34

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U3	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	26	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	3000 (GALLONS)	Tank Material:	UNKNOWN
Tank ID:	U4	Tank Status:	REMOVED
Tank Contents:	UNKNOWN	Leak Monitoring:	NO MONITOR
Tank Age:	10	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	260 (GALLONS)	Tank Material:	UNKNOWN
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1971		
Tank Removal Date:	08/01/1997		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: DENTON TANK RENTAL INC728 F. W. DRDENTON,TX 76201		
Tank ID#:	U1A		
Tank Installed Date / Age:	08/01/1997		
Description / Comment:	TANK MONITOR: VAPOR MONITORINGPIPE MONITOR: VAPOR MONITORING		
Description / Comment:	OWNER: DENTON TANK RENTAL INC728 F. W. DRDENTON,TX 76201		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1971		
Tank Removal Date:	08/01/1997		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: DENTON TANK RENTAL INC728 F. W. DRDENTON,TX 76201		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1971		
Tank Removal Date:	08/01/1997		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: DENTON TANK RENTAL INC728 F. W. DRDENTON,TX 76201		
Tank ID#:	U4		
Tank Installed Date / Age:	08/01/1987		
Tank Removal Date:	08/01/1997		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: DENTON TANK RENTAL INC728 F. W. DRDENTON,TX 76201		

VISTA Address*:	LAKELAND CITIES SHOPPING CTR/SPRITZ 603 S DENTON DR LAKE DALLAS, TX 75065	VISTA ID#:	4091316
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	LAKELAND CITIES SHOPPING CTR/SPRITZ 603 S DENTON DR LAKE DALLAS, TX 0053419		
Facility ID:	106674		
Leak ID#:	5/18/93		
Leak Report Date:	ARLINGTON		
Region / District:	FIRST COMMERCIAL REALTY		
Responsible Party:	MEDIA AFFECTED: GW IMPACT, PUB/DOM WATER SUPPLY WELL W/IN .25-.5 MIREMEDIATION STATUS: PHASE 3 IN PROGRESSRESPONSIBLE PARTY INFO: 2016 W JUSTIN RD,LEWISVILLE,TX,750777161,214/436-4643		
Description / Comment:			

Map ID

32



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #35

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0053419
Agency Address:		LAKELAND CITIES SHOPPING CENTER 603 S DENTON DR LAKE DALLAS, TX 75065	
Underground Tanks:		2	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	UA	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	20	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	UB	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	20	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	UA		
Tank Installed Date / Age:	06/01/1979		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: NONE		
Description / Comment:	OWNER: TEXMICH, INC. 132 W MAIN STLEWISVILLE, TX 75057		
Tank ID#:	UB		
Tank Installed Date / Age:	06/01/1979		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: NONE		
Description / Comment:	OWNER: TEXMICH, INC. 132 W MAIN STLEWISVILLE, TX 75057		

VISTA Address*:	BEER BARN 307 W HUNDLEY DR LAKE DALLAS, TX 75065	VISTA ID#:	5547520
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

33

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0038653
Agency Address:		SAME AS ABOVE	
Underground Tanks:		6	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		3	
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	8	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2B	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	8	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #36

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U3	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3C	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	8	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	07/01/1991		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		
Tank ID#:	U1A		
Tank Installed Date / Age:	07/01/1991		
Description / Comment:	TANK MONITOR: GROUNDWATER MONITORINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		
Tank ID#:	U2		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	07/01/1991		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		
Tank ID#:	U2B		
Tank Installed Date / Age:	07/01/1991		
Description / Comment:	TANK MONITOR: GROUNDWATER MONITORINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		
Tank ID#:	U3		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	07/01/1991		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		
Tank ID#:	U3C		
Tank Installed Date / Age:	07/01/1991		
Description / Comment:	TANK MONITOR: GROUNDWATER MONITORINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: MEE-NAAR INVESTMENT INCBOX 778LAKE DALLAS,TX 75065		

VISTA Address*:	SAMS GROCERY 307 W HUNDLEY DR LAKE DALLAS, TX 75065	VISTA ID#:	1399105
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0038653		
Leak ID#:	100423		
Leak Report Date:	9/3/91		
Region / District:	ARLINGTON		
Responsible Party:	FIRST INTERSTATE BANK (A T LEE		
Description / Comment:	MEDIA AFFECTED: MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAPREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: PO BOX 650291,DALLAS,TX,752650291,214/841-3210		

Map ID

33



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #37

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	PAYLESS CASHWAYS INC 500 N STEMMONS LAKE DALLAS, TX 75065	VISTA ID#:	1391417
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

34

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0030351		
Leak ID#:	092857		
Leak Report Date:	4/21/89		
Region / District:	ARLINGTON		
Responsible Party:	PAYLESS CASHWAYS INC		
Description / Comment:	MEDIA AFFECTED: NO GW IMPACT, NO APPARENT THREATS OR IMPACTS TORECEPTORSREMEDATION STATUS: INITIAL DIRECTIVES ISSUED A WAITING INITIALRESPONSERESPONSIBLE PARTY INFO: 500 N STEMMONS,LAKE DALLAS, TX, 75065, 817/430-8707		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0030351
Agency Address:	PAYLESS CASHWAYS, INC. 500 N STEMMONS LAKE DALLAS, TX 75065		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	16	Tank Piping:	STEEL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1983		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: PAYLESS CASHWAYS, INCPO BOX 419466KANSAS CITY,MO 641410466		

VISTA Address*:	ROADIES 1002 S STEMMONS LAKE DALLAS, TX 75065	VISTA ID#:	1813666
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

35

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0057931
Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	03/01/1985		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #38

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: AURORA, P. S.336 PARK VALLEY DRCOPPELL, TX 75019
Tank ID#:	U2
Tank Installed Date / Age:	03/01/1985
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: AURORA, P. S.336 PARK VALLEY DRCOPPELL, TX 75019
Tank ID#:	U3
Tank Installed Date / Age:	03/01/1985
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: AURORA, P. S.336 PARK VALLEY DRCOPPELL, TX 75019

VISTA Address*:	BOEING AEROSPACE ELECTR-CORINTH 7801 S STEMMONS LAKE DALLAS, TX 75065	VISTA ID#:	52676
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-LgGen - RCRA-Large Generator / SRC# 5596		EPA ID:	TXD982289415
Agency Address:	BOEING DEFENSE ELECTRONICS INC 7801 S STEMMONS CORINTH, TX 75065		
Generator Class:	Generates at least 1000 kg./month of non-acutely hazardous waste (or 1 kg./month of acutely hazardous waste).		

Map ID

35

VISTA Address*:	OSCAR RENDA 1500 TURBVILLE DENTON, TX 76205	VISTA ID#:	8536207
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
AST - Above Ground Storage Tank / SRC# 5627		Agency ID:	0070718
Agency Address:	SAME AS ABOVE		
Underground Tanks:	NOT REPORTED		
Aboveground Tanks:	1		
Tanks Removed:	NOT REPORTED		
Tank ID:	A1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NOT AVAILABLE
Tank Age:	1	Tank Piping:	UNKNOWN
Tank Size (Units):	2000 (GALLONS)	Tank Material:	UNKNOWN
Tank ID#:	A1		
Tank Installed Date / Age:	04/01/1998		
Description / Comment:	MONITOR TYPE: NOT APPLICABLE		
Description / Comment:	OWNER: REEDER DISTRIBUTORS, INC.PO BOX 8237FT WORTH, TX 761240237		

Map ID

36

VISTA Address*:	SHAMROCK ENTERPRISES 423 BULADORA LN LITTLE ELM, TX 75068	VISTA ID#:	4090941
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TXD988082707
Agency Address:	SHAMROCK ENTERPRISES 423 BULADORA LITTLE ELM, TX 75068		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

Map ID

37



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #39

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

RCRA-TSD / SRC# 5596		EPA ID:	TXD988082707
Agency Address:	SHAMROCK ENTERPRISES 423 BULADORA LITTLE ELM, TX 75068		
Off-Site Waste Received:	NO		
Land Disposal:	NO		
Incinerator:	NO		
Storage/Treatment:	NO		

VISTA Address*:	HILLARD'S GROCERY 70334 507 SHADY SHORES RD LAKE DALLAS, TX 75065	VISTA ID#:	6481432
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

38

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0006262
Agency Address:	SAME AS ABOVE		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	5000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	25	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	12	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1974		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1985		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		
Tank ID#:	U4		
Tank Installed Date / Age:	08/01/1987		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPLE A OIL CO., INC. 12342 INWOOD RDDALLAS, TX 75244		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #40

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	VIDEO PLUS INC 200 SWISHER RD LAKE DALLAS, TX 75065	VISTA ID#:	4899305
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

39

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0010680
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	TEMP OUT OF SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	6	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1984		
Tank Removal Date:	05/01/1990		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: VIDEO PLUS, INC. 200 SWISHER RD LAKE DALLAS, TX 75065		

VISTA Address*:	ROBINSON'S CONV STORE 201 KINGS RD FRISCO, TX 75034	VISTA ID#:	7066281
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

40

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0069768
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	UA	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	2	Tank Piping:	EXTERNAL JACKET SYSTEM
Tank Size (Units):	10000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID#:	UA		
Tank Installed Date / Age:	06/01/1997		
Description / Comment:	TANK MONITOR: GROUNDWATER MONITORING PIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: WATTS 201 KINGS RD FRISCO, TX 75034		

VISTA Address*:	LITTLE ELM ELEMENTARY MAIN STREET LAKESHORE LITTLE ELM, TX 75068	VISTA ID#:	246415
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point

Map ID

41

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0039948
Agency Address:	LITTLE ELM GROCERY 111 MAIN ST LITTLE ELM, TX 75068		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	3		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #41

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	ANTI-CORROSIVE
Tank Size (Units):	550 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1981		
Tank Removal Date:	08/01/1994		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: MONARCH ASSOCIATES P.O. BOX 486 FRISCO, TX 75034		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1981		
Tank Removal Date:	08/01/1994		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: MONARCH ASSOCIATES P.O. BOX 486 FRISCO, TX 75034		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1981		
Tank Removal Date:	08/01/1994		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: MONARCH ASSOCIATES P.O. BOX 486 FRISCO, TX 75034		

VISTA Address*:	LITTLE ELM ISD BUS FACILITY 411 LAKESHORE DR LITTLE ELM, TX 75068	VISTA ID#:	6480941
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
AST - Above Ground Storage Tank / SRC# 5627		Agency ID:	0050392

Map ID

42

Agency Address:	SAME AS ABOVE		
Underground Tanks:	2		
Aboveground Tanks:	3		
Tanks Removed:	4		
Tank ID:	A1	Tank Status:	TEMP OUT OF SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NOT AVAILABLE
Tank Age:	6	Tank Piping:	UNKNOWN
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	A2	Tank Status:	TEMP OUT OF SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NOT AVAILABLE
Tank Age:	2	Tank Piping:	UNKNOWN
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID:	A3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NOT AVAILABLE
Tank Age:	9	Tank Piping:	UNKNOWN
Tank Size (Units):	2000 (GALLONS)	Tank Material:	UNKNOWN
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #42

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	STEEL
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	A1		
Tank Installed Date / Age:	01/01/1986		
Tank Removal Date:	09/01/1992		
Description / Comment:	MONITOR TYPE: NOT APPLICABLE		
Description / Comment:	OWNER: LITTLE ELM ISD500 LOBOLITTLE ELM, TX 75068		
Tank ID#:	A2		
Tank Installed Date / Age:	01/01/1990		
Tank Removal Date:	09/01/1992		
Description / Comment:	MONITOR TYPE: NOT APPLICABLE		
Description / Comment:	OWNER: LITTLE ELM ISD500 LOBOLITTLE ELM, TX 75068		
Tank ID#:	A3		
Tank Installed Date / Age:	01/01/1990		
Description / Comment:	MONITOR TYPE: NOT APPLICABLE		
Description / Comment:	OWNER: LITTLE ELM ISD500 LOBOLITTLE ELM, TX 75068		
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	07/01/1990		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LITTLE ELM ISD500 LOBOLITTLE ELM, TX 75068		
Tank ID#:	U2		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	07/01/1990		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: LITTLE ELM ISD500 LOBOLITTLE ELM, TX 75068		

VISTA Address*:	MATLACK COMPANY *418 JONES AT UNITED RESI LONGVIEW, TX 75602	VISTA ID#:	5795008
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
State Spills / SRC# 4186		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region / District:	04		
Spiller Company:	MATLACK COMPANY		
Substance:	AIR FLEX 401 RESIN		
Quantity Spilled:	50 GAL	Spilled Units:	NOT REPORTED
Spill Cause:	EQUIPMENT FAILURE		
Spill Source:	001		
Water Body Affected:	NONE		
Remedial Status:	YES	Damages:	NOT REPORTED

Map ID

43



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #43

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	CRAIG OLDEN INC 661 E SHAHAN'S PRAIRIE RD LITTLE ELM, TX 75068	VISTA ID#:	1812473
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0053336
Agency Address:		SAME AS ABOVE	
Underground Tanks:		2	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		2	
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	12	Tank Piping:	STEEL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	12	Tank Piping:	STEEL
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1984		
Tank Removal Date:	08/01/1996		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CRAIG OLDEN INCP O BOX 5000 LITTLE ELM, TX 75068		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1984		
Tank Removal Date:	08/01/1996		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CRAIG OLDEN INCP O BOX 5000 LITTLE ELM, TX 75068		

Map ID

44

VISTA Address*:	STARLITE SIGN CO 7923 E MCKINNEY DENTON, TX 76208	VISTA ID#:	3971154
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
RCRA-SmGen - RCRA-Small Generator / SRC# 5596		EPA ID:	TXD007352230
Agency Address:		STARLITE SIGN CO 7923 E MCKINNEY DENTON, TX 76201	
Generator Class:		Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste	
AST - Above Ground Storage Tank / SRC# 5627		Agency ID:	0055248
Agency Address:		STARLITE SIGN OF DENTON, INC 7923 E MCKINNEY DENTON, TX 76208	
Underground Tanks:		NOT REPORTED	
Aboveground Tanks:		1	
Tanks Removed:		1	
Tank ID:	A1	Tank Status:	TEMP OUT OF SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NOT AVAILABLE
Tank Age:	5	Tank Piping:	UNKNOWN
Tank Size (Units):	2000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	A1		
Tank Installed Date / Age:	01/01/1990		
Tank Removal Date:	08/01/1995		
Description / Comment:	MONITOR TYPE: NOT APPLICABLE		
Description / Comment:	OWNER: C L SAND CO. INC14104 ARVIN HILL RDAUBREY, TX 76227		

Map ID

45



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #44

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	CORPS OF ENGINEERS 1.0 MI S OF SH-380 W OF FM-424 MARSHALL, TX 75670	VISTA ID#:	3050470
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE SWLF - Solid Waste Landfill / SRC# 5625		Agency ID:	00110
Agency Address:	CORPS OF ENGINEERS 1.0 MI S OF SH-380 W OF FM-424 CROSSROADS, TX		
Facility Type:	EXPERIMENTAL FACILITY		
Facility Status:	PROPOSED		
Facility Life:	NOT REPORTED		
Permit Status:	WITHDRAWN		
Waste:	NOT REPORTED		

Map ID

46

VISTA Address*:	DENTON, CITY OF ADJACENT MOSELY RD, 1.2MI S OF US 38 MARSHALL, TX 75670	VISTA ID#:	3048953
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE SWLF - Solid Waste Landfill / SRC# 5625		Agency ID:	00013
Agency Address:	DENTON, CITY OF ADJACENT MOSELY RD, 1.2MI S OF US 38 CROSSROADS, TX		
Facility Type:	SANITARY LANDFILL/LANDFILL		
Facility Status:	GRANDFATHER SITE		
Facility Life:	NOT REPORTED		
Permit Status:	PERMITTED/INACTIVE		
Waste:	NOT REPORTED		

Map ID

47

VISTA Address*:	NAVO GENERAL STORE 4899 HWY 380 LITTLE ELM, TX 75068	VISTA ID#:	6612126
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0007906
Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	16	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1983		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: TRIPWAL, L. C.250 N MILLEWISVILLE, TX 75067		
Tank ID#:	U2		

Map ID

48



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #45

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank Installed Date / Age:	01/01/1983
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: TRIPWAL, L. C.250 N MILLEWISVILLE, TX 75067
Tank ID#:	U3
Tank Installed Date / Age:	01/01/1983
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: TRIPWAL, L. C.250 N MILLEWISVILLE, TX 75067

VISTA Address*:	ABLE FUEL INJECTION SVC 1419 CRESENT AVE LEWISVILLE, TX 75053	VISTA ID#:	3017141
		Distance/Direction:	<0.01 MI / S
		Plotted as:	Point
RCRA-LgGen - RCRA-Large Generator / SRC# 5596		EPA ID:	TXD988066866
Agency Address:	ABLE FUEL INJECTION SVC 1419 CRESENT AVE LEWISVILLE, TX 75029		
Generator Class:	Generates at least 1000 kg./month of non-acutely hazardous waste (or 1 kg./month of acutely hazardous waste).		

Map ID

49

VISTA Address*:	LEWISVILLE WATER PROD. FACILITY 1400 N COWAN LEWISVILLE, TX 75057	VISTA ID#:	1389088
		Distance/Direction:	0.03 MI / S
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0027825
Agency Address:	LEWISVILLE WATER PROD. FACILITY 1400 N COWAN LEWISVILLE, TX 75067		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	25	Tank Piping:	STEEL
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1974		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LEWISVILLE P O BOX 299002LEWISVILLE, TX 750299002		

Map ID

50

VISTA Address*:	MCGEE'S COUNTRY STORE 1298 FM RD 407 LEWISVILLE, TX 75067	VISTA ID#:	1797534
		Distance/Direction:	0.04 MI / S
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0025399
Agency Address:	SAME AS ABOVE		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	16	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL

Map ID

51



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #46

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	22	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	22	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	22	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1983		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: BILLY BOB MCGEE1702 MCGEE LN LEWISVILLE, TX 75067		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1977		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: BILLY BOB MCGEE1702 MCGEE LN LEWISVILLE, TX 75067		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1977		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: BILLY BOB MCGEE1702 MCGEE LN LEWISVILLE, TX 75067		
Tank ID#:	U4		
Tank Installed Date / Age:	01/01/1977		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: BILLY BOB MCGEE1702 MCGEE LN LEWISVILLE, TX 75067		

VISTA Address*:	THE DEPOT 1175 JUSTIN RD FLOWER MOUND, TX 75028	VISTA ID#:	3668592
		Distance/Direction:	0.08 MI / S
		Plotted as:	Point

Map ID

51

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0062878
Agency Address:	SAME AS ABOVE		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #47

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	14	Tank Piping:	SINGLE WALL
Tank Size (Units):	10000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	03/01/1985		
Description / Comment:	TANK MONITOR: TIGHTNESS TESTINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: WALIANY, HASAN1175 JUSTIN RDFLOWER MOUND, TX 75028		
Tank ID#:	U2		
Tank Installed Date / Age:	03/01/1985		
Description / Comment:	TANK MONITOR: TIGHTNESS TESTINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: WALIANY, HASAN1175 JUSTIN RDFLOWER MOUND, TX 75028		
Tank ID#:	U3		
Tank Installed Date / Age:	03/01/1985		
Description / Comment:	TANK MONITOR: TIGHTNESS TESTINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: WALIANY, HASAN1175 JUSTIN RDFLOWER MOUND, TX 75028		
Tank ID#:	U4		
Tank Installed Date / Age:	03/01/1985		
Description / Comment:	TANK MONITOR: TIGHTNESS TESTINGPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: WALIANY, HASAN1175 JUSTIN RDFLOWER MOUND, TX 75028		

VISTA Address*:	PHIL DILL BOATS INC 1520 N STEMMONS LEWISVILLE, TX 75057	VISTA ID#:	328522
		Distance/Direction:	0.07 MI / S
		Plotted as:	Point

Map ID

52

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	PHIL DILL BOAT INC 1520 N STEMMONS LEWISVILLE, TX 75067		
Facility ID:	0000869		
Leak ID#:	102016		
Leak Report Date:	1/3/92		
Region / District:	ARLINGTON		
Responsible Party:	DILL PHIL BOAT INC		
Description / Comment:	MEDIA AFFECTED: MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIREDREMEDATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: 1520 N STEMMONS,LEWISVILLE, TX, 75067, 214/436-3581		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0000869
Agency Address:	PHIL DILL BOATS, INC. 1520 N STEMMONS LEWISVILLE, TX 75067		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	1		
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	16	Tank Piping:	STEEL
Tank Size (Units):	5000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1976		
Tank Removal Date:	01/01/1992		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: PHIL DILL BOATS, INC. 1520 N STEMMONSLEWISVILLE, TX 75067		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #48

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA Address*:	LAKE DALLAS SERVICE CENTER 3100 S GARRISON LAKE DALLAS, TX 75065		VISTA ID#:	1399601
			Distance/Direction:	0.08 MI / SW
			Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627			Agency ID:	0039202
Agency Address:		LAKE DALLAS SERVICE CENTER 3100 S GARRISON CORINTH, TX 750650998		
Underground Tanks:		3		
Aboveground Tanks:		NOT REPORTED		
Tanks Removed:		1		
Tank ID:	U1	Tank Status:	REMOVED	
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR	
Tank Age:	9	Tank Piping:	STEEL	
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL	
Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE	
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT	
Tank Age:	7	Tank Piping:	DOUBLE WALL, SINGLE WALL	
Tank Size (Units):	6000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC	
Tank ID:	U2A	Tank Status:	ACTIVE/IN SERVICE	
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT	
Tank Age:	7	Tank Piping:	DOUBLE WALL, SINGLE WALL	
Tank Size (Units):	6000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC	
Tank ID#:	U1			
Tank Installed Date / Age:	01/01/1983			
Tank Removal Date:	04/01/1992			
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE			
Description / Comment:	OWNER: TU ELECTRIC1601 BRYAN STDALLAS, TX 75201			
Tank ID#:	U1A			
Tank Installed Date / Age:	05/01/1992			
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROL PIPE MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL UST			
Description / Comment:	OWNER: TU ELECTRIC1601 BRYAN STDALLAS, TX 75201			
Tank ID#:	U2A			
Tank Installed Date / Age:	05/01/1992			
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROL PIPE MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL UST			
Description / Comment:	OWNER: TU ELECTRIC1601 BRYAN STDALLAS, TX 75201			

Map ID

53

VISTA Address*:	GTSW - LEWISVILLE PLANT FACILITY 1132 FM 407 LEWISVILLE, TX 75067		VISTA ID#:	5172878
			Distance/Direction:	0.10 MI / S
			Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627			Agency ID:	0022429
Agency Address:		SAME AS ABOVE		
Underground Tanks:		4		
Aboveground Tanks:		NOT REPORTED		
Tanks Removed:		2		
Tank ID:	U1	Tank Status:	REMOVED	
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT	
Tank Age:	NOT REPORTED	Tank Piping:	SINGLE WALL	
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL	

Map ID

54



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #49

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U1A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	7	Tank Piping:	DOUBLE WALL,DOUBLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	NOT REPORTED	Tank Piping:	SINGLE WALL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2A	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	7	Tank Piping:	DOUBLE WALL,DOUBLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	06/01/1992		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING,TX 75062		
Tank ID#:	U1A		
Tank Installed Date / Age:	06/01/1992		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING,TX 75062		
Tank ID#:	U2		
Tank Installed Date / Age:	UNRECORDED		
Tank Removal Date:	06/01/1992		
Description / Comment:	TANK MONITOR: TIGHTNESS TESTINGPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING,TX 75062		
Tank ID#:	U2A		
Tank Installed Date / Age:	06/01/1992		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING,TX 75062		

VISTA Address*:	GTE LEWISVILLE FACILITY 1132 FM 407 LEWISVILLE, TX 75067	VISTA ID#:	1798130
		Distance/Direction:	0.10 MI / S
		Plotted as:	Point

Map ID

54

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
---	----------------	-----

Agency Address:	SAME AS ABOVE
Facility ID:	0022429
Leak ID#:	104621
Leak Report Date:	9/14/92
Region / District:	ARLINGTON
Responsible Party:	GTE SOUTHWEST INC
Description / Comment:	MEDIA AFFECTED: IMPACTED GW W/IN 500FT-0.25MI TO SW USED BY HUMAN, ENDGR SPECREMEDATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: 290 E CARPENTER FWY,IRVING,TX,75062,214/717-7840

STATE UST - State Underground Storage Tank / SRC# 5627	Agency ID:	0057484
--	------------	---------

Agency Address:	GTE SW-LEWISVILLE GARDEN RIDGE 1128 FM 407 LEWISVILLE, TX 75067
Underground Tanks:	1
Aboveground Tanks:	NOT REPORTED
Tanks Removed:	NOT REPORTED



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #50

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	9	Tank Piping:	PROTECTED STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	11/01/1990		
Description / Comment:	TANK MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL USTPIPE MONITOR: NONE		
Description / Comment:	OWNER: GTE SOUTHWEST, INC.500 E CARPENTER FRWYIRVING,TX 75062		

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)

Map ID

55

VISTA Address*:	JOE'S COUNTRY STORE 7616 N MAIN THE COLONY, TX 75056	VISTA ID#:	6475880
		Distance/Direction:	0.13 MI / SE
		Plotted as:	Point

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
---	----------------	-----

Agency Address:	SAME AS ABOVE
Facility ID:	0058198
Leak ID#:	110351
Leak Report Date:	1/29/96
Region / District:	ARLINGTON
Responsible Party:	GITA KIANI
Description / Comment:	MEDIA AFFECTED: NO GW IMPACT, NO APPARENT THREATS OR IMPACTS TORECEPTORSREMEDATION STATUS: INITIAL DIRECTIVES ISSUED A WAITING INITIALRESPONSERESPONSIBLE PARTY INFO: 7616 N MAIN,THE COLONY,TX,75056,972/625-6431

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
---	----------------	-----

Agency Address:	SAME AS ABOVE
Facility ID:	0058198
Leak ID#:	112360
Leak Report Date:	6/6/97
Region / District:	ARLINGTON
Responsible Party:	GITA KIANI
Description / Comment:	MEDIA AFFECTED: IMPACTED GW W/IN 500FT-0.25MI TO SW USED BY HUMAN, ENDGR SPECREMEDATION STATUS: PENDING CLOSURE, WAITING FOR MONITORING CLOSURE REPORTRESPONSIBLE PARTY INFO: 7616 N MAIN,THE COLONY,TX,75056,972/625-6431

STATE UST - State Underground Storage Tank / SRC# 5627	Agency ID:	0058198
--	------------	---------

Agency Address:		JOES COUNTRY STORE 7616 N MAIN THE COLONY, TX 75056	
Underground Tanks:		2	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	10000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	18	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #51

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Tank Installed Date / Age:	01/01/1981
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: KIANIS-SAMADI, GITA7616 N MAINTHE COLONY, TX 75056
Tank ID#:	U2
Tank Installed Date / Age:	01/01/1981
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE
Description / Comment:	OWNER: KIANIS-SAMADI, GITA7616 N MAINTHE COLONY, TX 75056

VISTA Address*:	TRINTY CAR WASH 1450 W JUSTIN RD LEWISVILLE, TX 75067	VISTA ID#:	6883566
		Distance/Direction:	0.14 MI / S
		Plotted as:	Point

Map ID

56

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0068944
Agency Address:	SAME AS ABOVE		
Underground Tanks:	1		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	3	Tank Piping:	DOUBLE WALL, SINGLE WALL
Tank Size (Units):	15000 (GALLONS)	Tank Material:	FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	03/01/1996		
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: OASIS CARWASH CORPORATE OFFICEP O BOX 1187ADDISON, TX 75001		

VISTA Address*:	WEST TEX AUTO TIRE 1425 JUSTIN RD #350 LEWISVILLE, TX 75067	VISTA ID#:	1408958
		Distance/Direction:	0.15 MI / S
		Plotted as:	Point

Map ID

56

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0049513		
Leak ID#:	112459		
Leak Report Date:	10/29/96		
Region / District:	ARLINGTON		
Responsible Party:	WEST TEX SERVICE STATION LTD		
Description / Comment:	MEDIA AFFECTED: A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTEDREMEDATION STATUS: PHASE 2 IN PROGRESSRESPONSIBLE PARTY INFO: 6107 S COOPER ST, ARLINGTON, TX, 76001, 817/282-0972		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0049513
Agency Address:	WEST-TEX TIRE AUTO 1425 JUSTIN STE 950 RD LEWISVILLE, TX 75067		
Underground Tanks:	5		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #52

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	13	Tank Piping:	WALLED/DOUBLE WALLED
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U5	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	USED OIL	Leak Monitoring:	MONITOR PRESENT
Tank Age:	13	Tank Piping:	SINGLE WALL
Tank Size (Units):	500 (GALLONS)	Tank Material:	COMPOSITE,FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1986		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: WEST-TEX SERVICE STATION LTDP O BOX 150835ARLINGTON,TX 760156835		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1986		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: WEST-TEX SERVICE STATION LTDP O BOX 150835ARLINGTON,TX 760156835		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1986		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: WEST-TEX SERVICE STATION LTDP O BOX 150835ARLINGTON,TX 760156835		
Tank ID#:	U4		
Tank Installed Date / Age:	01/01/1986		
Description / Comment:	TANK MONITOR: NONEPIPE MONITOR: NONE		
Description / Comment:	OWNER: WEST-TEX SERVICE STATION LTDP O BOX 150835ARLINGTON,TX 760156835		
Tank ID#:	U5		
Tank Installed Date / Age:	03/01/1986		
Description / Comment:	TANK MONITOR: GROUNDWATER MONITORINGPIPE MONITOR: NONE		
Description / Comment:	OWNER: WEST-TEX SERVICE STATION LTDP O BOX 150835ARLINGTON,TX 760156835		

VISTA Address*:	EXXON STORE 6-0357 1501 W FM 407 LEWISVILLE, TX 75067	VISTA ID#:	7066672
		Distance/Direction:	0.17 MI / S
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0069844
Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	2	Tank Piping:	FIBERGLASS REINFORCED PLASTIC,DBL WALLED
Tank Size (Units):	12000 (GALLONS)	Tank Material:	OTHER

Map ID

56



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #53

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	2	Tank Piping:	FIBERGLASS REINFORCED PLASTIC, DBL WALLED
Tank Size (Units):	12000 (GALLONS)	Tank Material:	OTHER
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	2	Tank Piping:	FIBERGLASS REINFORCED PLASTIC, DBL WALLED
Tank Size (Units):	12000 (GALLONS)	Tank Material:	OTHER
Tank ID#:	U1		
Tank Installed Date / Age:	07/01/1997		
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROLPIPE MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL UST		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON, TX 772104386		
Tank ID#:	U2		
Tank Installed Date / Age:	07/01/1997		
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROLPIPE MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL UST		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON, TX 772104386		
Tank ID#:	U3		
Tank Installed Date / Age:	07/01/1997		
Description / Comment:	TANK MONITOR: AUTO IN-TANK MONITORING INVENTORY CONTROLPIPE MONITOR: INTERSTITIAL MONITORING FOR DOUBLE WALL UST		
Description / Comment:	OWNER: EXXON COMPANY USAPO BOX 4386HOUSTON, TX 772104386		

VISTA Address*:	KEN'S QUIK MART FOODS 7420 MAIN ST THE COLONY, TX 75056	VISTA ID#:	6883806
		Distance/Direction:	0.16 MI / SE
		Plotted as:	Point

Map ID

57

STATE UST - State Underground Storage Tank / SRC# 5627

Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	15	Tank Piping:	SINGLE WALL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	15	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	15	Tank Piping:	SINGLE WALL
Tank Size (Units):	NOT REPORTED (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1984		
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: TIGHTNESS TESTING		
Description / Comment:	OWNER: D. KAY JOHNSTON INC7420 MAIN THE COLONY, TX 75056		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1984		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #54

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: D. KAY JOHNSTON INC7420 MAINTHE COLONY, TX 75056
Tank ID#:	U3
Tank Installed Date / Age:	01/01/1984
Description / Comment:	TANK MONITOR: INVENTORY CONTROLPIPE MONITOR: LINE LEAK DETECTORS
Description / Comment:	OWNER: D. KAY JOHNSTON INC7420 MAINTHE COLONY, TX 75056

VISTA Address*:	MOBIL #12-147 6262 W MAIN ST THE COLONY, TX 75056	VISTA ID#:	6475878
		Distance/Direction:	0.17 MI / SE
		Plotted as:	Point

Map ID

58

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	MOBIL #12-147 6262 W MAIN ST LEWISVILLE, TX 0017660		
Facility ID:	0017660		
Leak ID#:	110522		
Region / District:	ARLINGTON		
Responsible Party:	MOBIL OIL		
Description / Comment:	MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDIAL STATUS: PHASE 2 REPORT RECEIVED, REVIEW PENDING RESPONSIBLE PARTY INFO: 4200 SINGLETON BLVD, DALLAS, TX, 75212, 214/905-1737		

VISTA Address*:	LEWISVILLE CITY OF 1100 N KEALY LEWISVILLE, TX 75057	VISTA ID#:	2574045
		Distance/Direction:	0.19 MI / S
		Plotted as:	Point

Map ID

59

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	LEWISVILLE CITY OF 1100 N KEALY LEWISVILLE, TX 75029		
Facility ID:	0027824		
Leak ID#:	101316		
Leak Report Date:	12/19/91		
Region / District:	ARLINGTON		
Responsible Party:	CITY OF LEWISVILLE		
Description / Comment:	MEDIA AFFECTED: MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAPREMIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSED RESPONSIBLE PARTY INFO: 1197 W MAIN, LEWISVILLE, TX, 214/219-3520		

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0027824
Agency Address:	CITY OF LEWISVILLE 1100 N KEALY LEWISVILLE, TX 75067		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	23	Tank Piping:	STEEL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	23	Tank Piping:	STEEL
Tank Size (Units):	8000 (GALLONS)	Tank Material:	STEEL



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #55

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	DIESEL	Leak Monitoring:	NO MONITOR
Tank Age:	23	Tank Piping:	STEEL
Tank Size (Units):	4000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U4	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	USED OIL	Leak Monitoring:	NO MONITOR
Tank Age:	23	Tank Piping:	STEEL
Tank Size (Units):	1000 (GALLONS)	Tank Material:	STEEL
Tank ID#:	U1		
Tank Installed Date / Age:	01/01/1976		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LEWISVILLE O BOX 299002 LEWISVILLE, TX 750299002		
Tank ID#:	U2		
Tank Installed Date / Age:	01/01/1976		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LEWISVILLE O BOX 299002 LEWISVILLE, TX 750299002		
Tank ID#:	U3		
Tank Installed Date / Age:	01/01/1976		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LEWISVILLE O BOX 299002 LEWISVILLE, TX 750299002		
Tank ID#:	U4		
Tank Installed Date / Age:	01/01/1976		
Description / Comment:	TANK MONITOR: NONE PIPE MONITOR: NONE		
Description / Comment:	OWNER: CITY OF LEWISVILLE O BOX 299002 LEWISVILLE, TX 750299002		

VISTA Address*:	UAC OF GARLAND, INC. 7228 MAIN ST THE COLONY, TX 75056	VISTA ID#:	2579974
		Distance/Direction:	0.20 MI / SE
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0059650

Map ID

60

Agency Address:		SAME AS ABOVE	
Underground Tanks:		2	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		2	
Tank ID:	U1	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	SINGLE WALL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID:	U2	Tank Status:	REMOVED
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	NO MONITOR
Tank Age:	NOT REPORTED	Tank Piping:	SINGLE WALL
Tank Size (Units):	3000 (GALLONS)	Tank Material:	STEEL
Tank ID#:		U1	
Tank Installed Date / Age:		UNRECORDED	
Tank Removal Date:		08/01/1991	
Description / Comment:		TANK MONITOR: NONEPIPE MONITOR: NONE	
Description / Comment:		OWNER: UAC OF GARLAND, INC.503 W HIGHLANDSOUTHLAKE,TX 76092	
Tank ID#:		U2	
Tank Installed Date / Age:		UNRECORDED	
Tank Removal Date:		08/01/1991	
Description / Comment:		TANK MONITOR: NONEPIPE MONITOR: NONE	



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #56

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

Description / Comment: OWNER: UAC OF GARLAND, INC. 503 W HIGHLANDSOUTH LAKE, TX 76092

VISTA Address*:	CLOSED FACILITY 7228 N MAIN ST THE COLONY, TX 75056	VISTA ID#:	2579973
		Distance/Direction:	0.20 MI / SE
		Plotted as:	Point

Map ID

60

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0059650		
Leak ID#:	100282		
Leak Report Date:	9/23/91		
Region / District:	ARLINGTON		
Responsible Party:	UAC OF GARLAND, INC.		
Description / Comment:	MEDIA AFFECTED: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS REMEDICATION STATUS: PHASE 3 IN PROGRESS RESPONSIBLE PARTY INFO: 503 W HIGHLAND, SOUTH LAKE, TX, 76092, 817/481-6381		

VISTA Address*:	C B EXPRESS 4250 E UNIVERSITY DENTON, TX 76208	VISTA ID#:	4555510
		Distance/Direction:	0.24 MI / NW
		Plotted as:	Point

Map ID

61

STATE UST - State Underground Storage Tank / SRC# 5627		Agency ID:	0065157
Agency Address:	C B EXPRESS 4250 E UNIVERSITY DENTON, TX 76201		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
Tank ID:	U1	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	10	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID:	U2	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	10	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID:	U3	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	GASOLINE (UNSPECIFIED)	Leak Monitoring:	MONITOR PRESENT
Tank Age:	10	Tank Piping:	SINGLE WALL
Tank Size (Units):	6000 (GALLONS)	Tank Material:	COMPOSITE, FIBERGLASS REINFORCED PLASTIC
Tank ID#:	U1		
Tank Installed Date / Age:	09/01/1989		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: LILLARD, G T617 MAGNOLIA ST DENTON, TX 762010822		
Tank ID#:	U2		
Tank Installed Date / Age:	09/01/1989		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: LILLARD, G T617 MAGNOLIA ST DENTON, TX 762010822		
Tank ID#:	U3		
Tank Installed Date / Age:	09/01/1989		
Description / Comment:	TANK MONITOR: INVENTORY CONTROL PIPE MONITOR: LINE LEAK DETECTORS		
Description / Comment:	OWNER: LILLARD, G T617 MAGNOLIA ST DENTON, TX 762010822		



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #57

SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.

VISTA Address*:	STOP N GO #1127 4610 FM 423 THE COLONY, TX 75056	VISTA ID#:	5109461
		Distance/Direction:	0.24 MI / SE
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	0039401		
Leak ID#:	107152		
Leak Report Date:	7/14/93		
Region / District:	ARLINGTON		
Responsible Party:	NATIONAL CONVENIENCE STORES		
Description / Comment:	MEDIA AFFECTED: GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATIONINCOMPLETEREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: PO BOX 758,HOUSTON,TX,770010758,713/863-2318		

Map ID

62

SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)

VISTA Address*:	HOWDY DOODY GRO 1026 N MILL LEWISVILLE, TX 75057	VISTA ID#:	6982928
		Distance/Direction:	0.28 MI / S
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	HOWDY DOODY GRO 1026 N MILL LEWISVILLE, TX 75067		
Facility ID:	0007914		
Leak ID#:	091680		
Leak Report Date:	2/22/88		
Region / District:	ARLINGTON		
Responsible Party:	KELSOE OIL COMPANY		
Description / Comment:	MEDIA AFFECTED: GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATIONINCOMPLETEREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: P.O. DRAWER R,DENTON,TX,76202,817/387-3804		

Map ID

63

VISTA Address*:	CLOSED HOWDY-DOODY STORE 1026 N MILL ST LEWISVILLE, TX 75057	VISTA ID#:	2577973
		Distance/Direction:	0.28 MI / S
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 5626		EPA/Agency ID:	N/A
Agency Address:	CLOSED HOWDY-DOODY STORE 1026 N MILL ST LEWISVILLE, TX 75067		
Facility ID:	0007914		
Leak ID#:	099797		
Leak Report Date:	6/26/91		
Region / District:	ARLINGTON		
Responsible Party:	ARTIN MINASSIAN		
Description / Comment:	MEDIA AFFECTED: IMPACTED GW W/IN 500FT-0.25MI TO SW USED BY HUMAN, ENDGR SPECREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: 842 S VALLEY PKWY,LEWISVILLE,TX,75067,214/436-7250		

Map ID

63



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #58

SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.

Map ID

64

VISTA Address*:	VILLAGE FORD 1144 N STEMMONS FRWY LEWISVILLE, TX 75057	VISTA ID#:	162121
		Distance/Direction:	0.35 MI / S
		Plotted as:	Point

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
--	----------------	-----

Agency Address:	FRONTIER FORD INC 1144 N STEMMONS FWY LEWISVILLE, TX 75067
Facility ID:	0012588
Leak ID#:	095426
Leak Report Date:	2/12/90
Region / District:	ARLINGTON
Responsible Party:	FRONTIER FORD WGW LTD
Description / Comment:	MEDIA AFFECTED: SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT RAPREMEDIATION STATUS: INITIAL DIRECTIVES ISSUED A WAITING INITIALRESPONSERESPONSIBLE PARTY INFO: 900 JACKSON ST,DALLAS,TX,75202,214/747-2550

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
--	----------------	-----

Agency Address:	FRONTIER FORD 1144 STEMMONS FWY LEWISVILLE, TX 75067
Facility ID:	0012588
Leak ID#:	098427
Leak Report Date:	7/24/91
Region / District:	ARLINGTON
Responsible Party:	FDIC
Description / Comment:	MEDIA AFFECTED: GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATIONINCOMPLETEREMEDIATION STATUS: FINAL CONCURRENCE ISSUED, CASE CLOSEDRESPONSIBLE PARTY INFO: 1910 PACIFIC AVE STE 1300,DALLAS,TX,752014586,214/385-3701

Map ID

65

VISTA Address*:	NORTHWEST BUTANE 9001 FM 423 FRISCO, TX 75034	VISTA ID#:	1798136
		Distance/Direction:	0.41 MI / E
		Plotted as:	Point

STATE LUST - State Leaking Underground Storage Tank / SRC# 5626	EPA/Agency ID:	N/A
--	----------------	-----

Agency Address:	NORTHWEST BUTANE 9001 FM 423 FRISCO, TX
Facility ID:	0055695
Leak ID#:	108267
Leak Report Date:	6/16/94
Region / District:	ARLINGTON
Responsible Party:	NORTHWEST BUTANE GAS CO
Description / Comment:	MEDIA AFFECTED: NO GW IMPACT, NO APPARENT THREATS OR IMPACTS TORECEPTORSREMIATION STATUS: INITIAL DIRECTIVES ISSUED A WAITING INITIALRESPONSERESPONSIBLE PARTY INFO: 11551 HARRY HINES BLVD,DALLAS,TX,75229,214/247-6121

SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)

No Records Found



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #59

UNMAPPED SITES

VISTA Address*:	H L MIZE BOX 846 LAKE DALLAS, TX 75065	VISTA ID#:	196648
NFRAP / SRC# 5595		EPA ID:	TXD981048341
Agency Address:	SAME AS ABOVE		
Site Description:	THE SITE IS THE LOCATION OF A PESTICIDE APPLICATOR WHERE HAZARDOUS WASTE MAY BE TREATED, STORED OR DISPOSED.		
EPA Region:	6		
Congressional District:	0		
Federal Facility:	Agency Code ()		
Facility Ownership:	OTHER		
Site Incident Category:	unknown		
Federal Facility Docket:	SITE IS NOT INCLUDED ON THE DOCKET		
NPL Status:	NOT ON NPL		
Incident Type:	Unknown		
Proposed NPL Update #:	0		
Final NPL Update #:	0		
Financial Management System ID:	NOT REPORTED		
Latitude:	0		
Longitude:	0		
Lat/Long Source:	Agency Code ()		
Lat/Long Accuracy:	Unknown		
Dioxin Tier:	Unknown		
USGS Hydro Unit:	12030103		
RCRA Indicator:	Unknown		
Unit Id:	0		
Unit Name:	ENTIRE SITE		
Type:	DISCOVERY	Lead Agency:	EPA FUND-FINANCED
Qualifier:	UNKNOWN	Category:	Unknown
Name:	NOT REPORTED	Actual Start Date:	NOT REPORTED
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	PRELIMINARY ASSESSMENT	Lead Agency:	STATE, FUND FINANCED
Qualifier:	NO FURTHER REMEDIAL ACTION PLANNED	Category:	Unknown
Name:	NOT REPORTED	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 243584-001

Version 2.6

Date of Report: May 6, 1999

Page #60

SITE ASSESSMENT - SPECIAL REPORT

DESCRIPTION OF DATABASES SEARCHED

A) DATABASES SEARCHED TO 1 MILE

NPL
SRC#: 5691

VISTA conducts a database search to identify all sites within 1 mile of your property.
The agency release date for NPL was March, 1999.

The National Priorities List (NPL) is the EPA's database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Dept of Health and Human Services and the US EPA in order to become an NPL site.

SPL
SRC#: 5254

VISTA conducts a database search to identify all sites within 1 mile of your property.
The agency release date for State Superfund Program was July, 1998.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-2458.

CORRACTS
SRC#: 5596

VISTA conducts a database search to identify all sites within 1 mile of your property.
The agency release date for HWDMS/RCRIS was February, 1999.

The EPA maintains this database of RCRA facilities which are undergoing "corrective action". A "corrective action order" is issued pursuant to RCRA Section 3008 (h) when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.

B) DATABASES SEARCHED TO 1/2 MILE

CERCLIS
SRC#: 5594

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for CERCLIS was January, 1999.

The CERCLIS List contains sites which are either proposed to or on the National Priorities List(NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL. The information on each site includes a history of all pre-remedial, remedial, removal and community relations activities or events at the site, financial funding information for the events, and unrestricted enforcement activities.

NFRAP
SRC#: 5595

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for CERCLIS-NFRAP was January, 1999.

NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly, or the contamination was not serious enough to require Federal Superfund action or NPL consideration.

SCL
SRC#: 5705

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for Voluntary Cleanup Program Site Listing was March, 1999.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-5891.



RCRA-TSD
SRC#: 5596

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for HWDMS/RCRIS was February, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA TSDs are facilities which treat, store and/or dispose of hazardous waste.

SWLF
SRC#: 5625

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for Solid Waste Facilities Permit Applications File was January, 1999.

This database is provided by the Natural Resource Conservation Commission, Division of MSW. The agency may be contacted at: 512-239-6067.

LUST
SRC#: 5626

VISTA conducts a database search to identify all sites within 1/2 mile of your property.
The agency release date for Leaking Petroleum Storage Tank Case Report was January, 1999.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-0986.

C) DATABASES SEARCHED TO 1/4 MILE

UST's
SRC#: 5627

VISTA conducts a database search to identify all sites within 1/4 mile of your property.
The agency release date for Petroleum Storage Tank Database was January, 1999.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-0986; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

AST's
SRC#: 5627

VISTA conducts a database search to identify all sites within 1/4 mile of your property.
The agency release date for Aboveground Storage Tank Database was January, 1999.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-0986.

D) DATABASES SEARCHED TO 1/8 MILE

ERNS
SRC#: 5598

VISTA conducts a database search to identify all sites within 1/8 mile of your property.
The agency release date for was December, 1998.

The Emergency Response Notification System (ERNS) is a national database containing records from October 1986 to the release date above and is used to collect information for reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the US Coast Guard, the National Response Center and the Department of Transportation. The ERNS hotline number is (202) 260-2342.

RCRA-LgGen
SRC#: 5596

VISTA conducts a database search to identify all sites within 1/8 mile of your property.
The agency release date for HWDMS/RCRIS was February, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Large Generators are facilities which generate at least 1000 kg./month of non-acutely hazardous waste (or 1 kg./month of acutely hazardous waste).



RCRA-SmGen
SRC#: 5596

VISTA conducts a database search to identify all sites within 1/8 mile of your property.
The agency release date for HWDMS/RCRIS was February, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Small and Very Small generators are facilities which generate less than 1000 kg./month of non-acutely hazardous waste.


SPILL
SRC#: 4186

VISTA conducts a database search to identify all sites within 1/8 mile of your property.
The agency release date for Spills Incident Information System was October, 1997.

This database is provided by the Natural Resource Conservation Commission. The agency may be contacted at: 512-239-2446.


End of Report





SITE ASSESSMENT - SPECIAL REPORT

Overview Map



Subject
Centerline

Search Area


Risk Sites

Risk Sites Plotted
as Polygons



Highways and Major Roads


Rivers or Water Bodies

Categories correspond to database searches described in
the Site Distribution Summary, beginning on Page #1.




SITE ASSESSMENT - SPECIAL REPORT






SITE ASSESSMENT - SPECIAL REPORT

Overview Map



Subject
Centerline




Search Area

Risk Sites




Risk Sites Plotted
as Polygons



Highways and Major Roads


Rivers or Water Bodies

















Categories correspond to database searches described in
the Site Distribution Summary, beginning on Page #1.



SITE ASSESSMENT - SPECIAL REPORT

Detail Map 1




Subject Centerline	Category:	A	B	C	D	Risk Sites Plotted as Polygons
	Single Sites					
	Multiple Sites					
	Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.					
						
						
						
						

For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403

Report ID: 243584001


Date of Report: August 17, 1999

Page #4a




SITE ASSESSMENT - SPECIAL REPORT

Detail Map 2




<div>Subject Centerline</div> <div></div> <div>Search Area</div> <div></div>	<div>Category:</div> <div>A</div> <div>B</div> <div>C</div> <div>D</div> <div>Risk Sites Plotted as Polygons</div>
<div>Single Sites</div> <div>Multiple Sites</div>	<div></div> <div></div> <div></div> <div></div> <div></div>
<div></div> <div>Highways and Major Roads</div> <div></div> <div>Roads</div> <div></div> <div>Railroads</div> <div></div> <div>Rivers or Water Bodies</div> <div></div> <div>Utilities</div>	<div>Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.</div>




SITE ASSESSMENT - SPECIAL REPORT

Detail Map 3




<p>Subject Centerline</p> <p>Search Area</p>	<p>Category:</p> <p>A</p> <p>Single Sites</p> <p>Multiple Sites</p>	<p>B</p>	<p>C</p>	<p>D</p>	<p>Risk Sites Plotted as Polygons</p>
Highways and Major Roads Roads Railroads Rivers or Water Bodies Utilities	<p>Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.</p>				



SITE ASSESSMENT - SPECIAL REPORT

Detail Map 4




Subject Centerline	Category:	A	B	C	D	Risk Sites Plotted as Polygons
	Single Sites					
	Multiple Sites					
	Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.					

For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403

Report ID: 243584001



Date of Report: August 17, 1999


Page #4d



SITE ASSESSMENT - SPECIAL REPORT



Detail Map 5






SITE ASSESSMENT - SPECIAL REPORT


Detail Map 6






















SITE ASSESSMENT - SPECIAL REPORT

Detail Map 7






Subject Centerline	Category:	A	B	C	D	Risk Sites Plotted as Polygons
	Single Sites					
	Multiple Sites					
    	Highways and Major Roads Roads Railroads Rivers or Water Bodies Utilities	Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.				



SITE ASSESSMENT - SPECIAL REPORT


Detail Map 8





















SITE ASSESSMENT - SPECIAL REPORT


Detail Map 9



Subject Centerline	Category:	A	B	C	D	Risk Sites Plotted as Polygons
	Single Sites					
	Multiple Sites					
 Highways and Major Roads  Roads  Railroads  Rivers or Water Bodies  Utilities						
Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.						

SITE ASSESSMENT - SPECIAL REPORT

Detail Map 10




For More Information Call VISTA Information Solutions, Inc. at **1 - 800 - 767 - 0403**

Report ID: 243584001


Date of Report: **August 17, 1999**

Page #4j








SITE ASSESSMENT - SPECIAL REPORT

Detail Map 11



Subject Centerline	Category:				Risk Sites Plotted as Polygons
Search Area	A	B	C	D	
	Single Sites				
	Multiple Sites				
Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.					


	Highways and Major Roads
	Roads
	Railroads
	Rivers or Water Bodies
	Utilities

For More Information Call VISTA Information Solutions, Inc. at **1 - 800 - 767 - 0403**

Report ID: **243584001**



Date of Report: **August 17, 1999**

Page #4k




SITE ASSESSMENT - SPECIAL REPORT

Detail Map 13




SITE ASSESSMENT - SPECIAL REPORT

Detail Map 14



Subject
Centerline



Search Area

Category:

Single Sites

Multiple Sites

A



B



C



D



Risk Sites Plotted as Polygons



Highways and Major Roads


Roads

Railroads

Rivers or Water Bodies


Utilities


Categories correspond to database searches described in the Site Distribution Summary, beginning on Page #1.



SITE ASSESSMENT - SPECIAL REPORT



Detail Map 15





SITE ASSESSMENT - SPECIAL REPORT

Detail Map 16




For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403

Report ID: 243584001

Date of Report: August 17, 1999

Page #4p



SITE ASSESSMENT - SPECIAL REPORT

Detail Map 17

